

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

A23
SW
< 1/8
0.055 mi.
288 ft.

CON EDISON MANHOLE #64659
NEPTUNE AVE AND WEST 12TH ST
BROOKLYN, NY

NY Spills S121119129
N/A

Site 22 of 23 in cluster A

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: CON EDISON MANHOLE #64659
Address: NEPTUNE AVE AND WEST 12TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1706173 / 2017-11-10
Facility ID: 1706173
Facility Type: ER
DER Facility ID: 513973
Site ID: 560477
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 2401
Spill Date: 2017-09-25
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2017-09-25
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2017-09-25
Spill Record Last Update: 2017-11-10
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CHRIS
DEC Memo: "10/4/17-Vought-Vought noted this spill as unassigned during performance of weekly spill statistics. Vought added EMIS #261522 to Cross Reference field and as per EMIS Cable crew reported on location to remove a section of feeder 11B01 found 10 gallons of unknown oil on top of 100gallons water contained to the structure. Sure access location, structure located on sidewalk. Crew placed Env tag 41030 and took pcb/oil ID samples under COC HH34766. Crew using WR 3280821 for the cable removal.'. Spill assigned to Con Edison Unassigned. 11/10/17 - Austin - Con Ed contained and cleaned up the spill, and removed solid waste debris; no source of the oil was found after the cleanup - See document files for further information - Spill closed - end"

Remarks: "contained and clean up is pending results"

All Materials:

Site ID: 560477
Operable Unit ID: 1308474
Operable Unit: 01
Material ID: 2315428
Material Code: 0066A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported